

CAE-860111**250-C28B*****Sunrise Helicopter, Inc. Time / Cycle Record*****(281) 251-4005** **www.sunrisehelicopter.com****Hours Remaining: 236.00****Cycles Remaining: 618****Serial Number:** CAE-860111**Assembly TT:** 18509.60**Assembly TC:** 12892**Engine Model:** 250-C28B**Assembly TSO:** 1264.00**Assembly CSO:** 1902**Part Number:** 6895000**Cycle Counter Reading and Date:****Container Number:** 120**Current Location:** SUNRISE HELICOPTER, INC

NOMENCLATURE	RECORD UPDATED	PART NUMBER	SERIAL NUMBER	TOTAL TIME	MAXIMUM OPERATING HOURS	TOTAL CYCLES	MAXIMUM CYCLES	TSO	TSI	CSO
TURBINE	12/11/2008	23031899	CAT-70186	13617.70	1500	23517		1264.00		2319
#1 WHEEL	12/11/2008	6895801	X122842	1264.00	1550	2319	3000			
#2 WHEEL	12/11/2008	23004223	HX115988	1264.00	1550	2319	3000			
#3 WHEEL	12/11/2008	6899383	HX91964	1011.50	4550	1902	6000			
#4 WHEEL	12/11/2008	6889054	HX61661	2347.90	4550	5382	6000			
COMPRESSOR	12/11/2008	23005200	CAC-70689	4875.60		5740		174.50		
IMPELLER	12/11/2008	6899355	LP61143	6843.60	15000	12052	25000			
GEARBOX	12/11/2008	23053985	CAG-70217					1297.40	1297.40	
FUEL CONTROL	12/11/2008	23065144	330250		2500			1105.20		
GOVERNOR	12/11/2008	2524677-12	22076		2000			321.50		
FUEL PUMP	12/11/2008	6896822	T200056		3000			1382.30		
FUEL NOZZLE	12/11/2008	23077067	0007		2000			140.10		
BLEED VALVE	12/11/2008	23005367	FF-36522		1500			274.05		
(reserved)										

INSPECTIONS AND REPLACEMENTS DUE

	ENGINE TT	ENGINE TC
100 HR INSP DUE:	18609.60	
300 HR INSP DUE:	18809.60	
TURBINE SHAFTING INSP DUE:	19869.80	
COMPRESSOR SHAFTING INSP:	19869.80	
GEARBOX INSPECTION DUE:		
FUEL NOZZLE OH DUE:	20369.50	
FUEL NOZZLE TEST/CLEAN DUE:	18809.60	
#1 WHEEL DUE:	18795.60	13573
#2 WHEEL DUE:	18795.60	13573
#3 WHEEL DUE:	22048.10	16990
#4 WHEEL DUE:	20711.70	13510
TIE BOLT DUE:	NA	
IMPELLER DUE:	26666.00	25840
SPECIAL DUE: CEB-A-72-2193		

RENTAL TIME SHEET NOTES*Note 1:* #3 WHEEL HX91964 INSTALLED ON 10-08-04 - GOOD*Note 2:* GEARBOX CAG-70217 TSI-1297.4 AS LOGCARDS SAY TSI 0.0 AT TT 17004.0 ON 3-14-2000 BUT DOES NOT SAY A 3500 HR INSPECTION WAS PERFORMED, ONLY C/W CEB-2179 R2.*Note 3:* GEARBOX CEB-72-2139 AND 2199 NOT COMPLIED WITH**CUSTOMER:** _____ **Date:** _____**Installed at Airframe Time:** _____ **Cycle Counter Reading at Installation:** _____**Removed at Airframe Time:** _____ **Cycle Counter Reading at Removal:** _____**Time Run:** _____ **Cycles Used:** _____