

# ENGINE SERVICE AND

| DATE                                                   | TIME RUN |      | TIME SINCE OVERHAUL |      | INSTALLATIONS, INSPECTIONS,<br><small>NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE</small> |
|--------------------------------------------------------|----------|------|---------------------|------|---------------------------------------------------------------------------------------------------------------|
|                                                        | HRS.     | MIN. | HRS.                | MIN. |                                                                                                               |
| BROUGHT FORWARD <span style="font-size: 2em;">→</span> |          |      |                     |      |                                                                                                               |

### FAA MAINTENANCE RELEASE

|                 |                   |                      |         |
|-----------------|-------------------|----------------------|---------|
| Acft.Reg.#      | N/A               |                      |         |
| Nomenclature:   | Reduction Gearbox | Part Number:         | 3024780 |
| Serial Number:  | CP-GB 2594        | Quantity:            | 1       |
| Time Since New: | 11,859.2          | Time Since Overhaul: | 3,565.6 |
| CSN             | N/A               | CSO                  | N/A     |

**Work Accomplished:**

Complied with Mint Turbines LLC Rental Return Inspection (FRM-160) as well as the required Periodic Inspections (100hr, 150hr, 200hr, done IAW PWC MM 3017042 Rev 42).

The item (s) listed above was Inspected in accordance with manufacturers specifications and current regulations of the Federal Aviation Administration. In respect to the work performed, the item(s) have been determined to be in airworthy condition and approved for return to service for time to continue. Pertinent details of work performed are on file under Mint Turbines LLC Work Order 6801 Dated Oct 24, 2012.

|                                                                                                                                                                 |                                  |                                                                                 |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|---------------------------------------------------------------------------------|
| <p><b>MINT TURBINES LLC</b><br/>                 P.O. Box 460<br/>                 Stroud, Oklahoma 74079<br/>                 FAA Repair Station #5MNR431B</p> | Authorized Signature & Stamp<br> | Date:<br>Oct 24 2012 <div style="text-align: center; margin-top: 10px;"> </div> |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|---------------------------------------------------------------------------------|

|  |  |  |  |  |  |
|--|--|--|--|--|--|
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |

**ASCENT AEROSPACE LTD.**  
 Qualicum Beach, British Columbia  
 Canada

D.O.T. App. No. 87-06

Ref. No. 12-368

Nomenclature COMBINING GEARBOX Type/Model \_\_\_\_\_

Manufacturer P&W S/N CPGB-2594

P/N 3024780 TSO 3565.6

Total Time 11,859.2 T.Rem. \_\_\_\_\_

Overhaul  Repair  Modification  Insp.  Removal

Previous Certification C-GWUL

The maintenance described has been performed in accordance with the applicable standards of airworthiness.

02 OCT. 2012 License No./Stamp \_\_\_\_\_

Date Signature Authorized Inspector

*Details of outstanding work and other information on reverse*

MAINTENANCE RELEASE